

**From:** [Melvin Dimick \(Bud\)](#)  
**To:** [Langenfeld, Matthew](#); [EPA Region 8 Drinking Water Unit](#)  
**Subject:** Out of compliance notification for PWSID # WY5600045  
**Date:** Thursday, August 10, 2023 1:06:39 PM

---

Good afternoon,

I am sending you an update on the out of compliance letter for three significant deficiencies we failed to address on our 2020 sanitary survey. They were as follows:

1. Gravity Tank ID: ST01 The bottom of the vent screen must be at least 8" above the roof.
2. Gravity Tank ID: ST05-The bottom of the vent screen must be at least 8" above the roof.
3. Gravity Tank ID: ST06-The clear well tank must be cleaned and inspected.

The clear well was inspected and cleaned on June 26<sup>th</sup>, 2023, and we are awaiting the written report and pictures from the contractor. These will be sent to you as soon as we receive them.

The shrouds on the vents of the two storage tanks have been cut from the tank roof and materials have been ordered to install downturned elbows with screen openings 24" above the tank roof. This will be done as soon as we receive the materials and pictures will be submitted.

Public notices are being processed and notifications will be sent out according to EPA instructions.

Thank you,

Bud Dimick  
City of Rawlins  
PWSID # WY5600045  
[Water/Wastewater](#) Superintendent  
915 3<sup>rd</sup> Street  
Rawlins, WY 82301  
Public Works: 307-328-4599  
Water Plant: 307-328-4564  
Cell: 307-321-3645